

MODELO DE IMPRESSÃO



PROJETO GRÁFICO: REGINALDO
 ATUALIZADO EM: 03/06/14
 VALIDADO EM: 00/00/14
 UNIDADE: MILÍMETROS
 FORMATO ABERTO: 950x680
 FORMATO FECHADO: 460x545x105
 FACA: EE-VERSO

CÓDIGOS:

SACO: 362324
 PI: 362312
 PPIP: 362322

CLI0006950

1ª Cor
VD-10

 GTT-XL
 ÁREA cm²
 378,050

2ª Cor
BS-01

 GTT-XL
 ÁREA cm²
 904,580

PATCH IMPRESSO →

**FERROUS SULFATE
 HEPTAHYDRATE
 (WITH ANTI-CAKING)**

460x545x105
 01 KNE 88 + 01 LAM 88+10
 MÁQUINA
 DATA
 TURNO

V
A
R
I
A
N
T
E



♦ Diamond Brand® ♦ Diamond Brand® ♦ Diamond Brand® ♦ Diamond Brand® ♦

**FERROUS SULFATE
 HEPTAHYDRATE**

Other than USP Grade
 Guaranteed Analysis
 Iron (Fe)20%
 20% Water Soluble Iron (Fe)
 Derived From: Ferrous Sulfate

Information regarding the contents and levels of metals in
 this product is available on the Internet at
<http://www.aapfco.org/metals.htm>.

F1101

50 LBS. NET (22.68 kg)

CAS #7782-63-0

IN CASE OF CHEMICAL EMERGENCY CALL CHEMTREC DAY OR NIGHT 1-800-424-9300
 DISTRIBUTED BY



Produced In The U.S.A.

For additional information find us at www.qccorporation.com or e-mail us at info@qccorporation.com

♦ Diamond Brand® ♦ Diamond Brand® ♦ Diamond Brand® ♦ Diamond Brand® ♦

CAPE GIRARDEAU, MO 63701

DIAMOND BRAND®



The manufacturer makes no representation or
 warranty, expressed or implied, and shall not be
 responsible for any injury to person or property
 resulting from the use, or misuse, of this material.

♦ Diamond Brand® ♦ Diamond Brand® ♦ Diamond Brand® ♦

WARNING

FIRST AID:
 If swallowed: Contact physician or poison control center
 immediately.
 If in eyes: Flush with water for 15 minutes.
 If inhaled: Contact physician immediately.
 In case of skin contact: Flush with water for 15 minutes.
 Toxicological information: Treat symptomatically.

PRECAUTIONS:
 Avoid breathing. May cause irritation to eyes and
 respiratory tract. Will stain porous surfaces such as
 concrete, wood and metal when exposed to free
 moisture such as water. When handling and storing wear
 gloves, safety goggles, a breathing mask and coveralls.

STORAGE:
 Stored materials should be placed in a dry and
 reasonably temperatured area, preferably below 75°F.

DECONTAMINATION AND DISPOSAL:
 Canadian formulators using this product should dispose
 of unwanted active ingredient and containers in accordance
 with municipal or provincial regulations. For
 additional details and cleanup of spills, contact the
 regional office of Environmental Protection,
 Environment Canada.

NOTICE TO USER:
 This product is to be used only in accordance with the
 precautions on this label.

SEE MATERIAL SAFETY DATA SHEET

♦ Diamond Brand® ♦ Diamond Brand® ♦ Diamond Brand® ♦

MANUFACTURED FOR
 QC CORPORATION
 BY
 ADD-IRON CORPORATION
 730 MILEY ROAD
 NORTH LIMA, OHIO 44452
 Telephone 573-335-6700



FREIGHT SHIPPING BAG
 Meeting Requirements of
 APPLICABLE FREIGHT CLASSIFICATION
 Operated by
 UNITED BAGS, INC.
 ST. LOUIS, MISSOURI
 TO REORDER CALL 314-421-3700

18Q7 264 25 MFG DATE 2013.09.01
 02 1NE 578
 01 HDPE 10

ATENÇÃO
 IMPRIMIR MÊS E ANO DA
 OPERAÇÃO DE IMPRESSÃO
 EXEMPLO: 09/2013

PATCH IMPRESSO →

**FERROUS SULFATE
 HEPTAHYDRATE
 (WITH ANTI-CAKING)**

15
 4

5

80

360

Ferrous Sulfate Heptahydrate
QC Corporation, 5566 Nash Rd, Cape Girardeau, MO 63701, USA
In case of chemical emergency call Chemtrec day or night 800-424-9300



Warning

Harmful if swallowed
Causes skin irritation
Causes serious eye irritation

Wash skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/ eye protection/face protection. **FIRST AID:** IF SWALLOWED, call a poison center or doctor/physician if you feel unwell. IF ON SKIN, wash with plenty of soap and water. IF IN EYES, rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Specific treatment (see supplemental first aid instructions on this label). IF SKIN IRRITATION OCCURS, get medical advice/ attention. IF EYE IRRITATION PERSISTS, get medical advice/attention. Take off contaminated clothing and wash before reuse. **Storage and Disposal:** Stored materials should be placed in a dry and reasonably temperature area, preferably below 75°F. Dispose of contents/container to an approved waste disposal plant.

Net Weight /Contents: 50 Lbs. (22.68 Kgs)

Precautions: Will stain porous surfaces such as concrete, wood and metal when exposed to free moisture such as water.

SEE SAFETY DATA SHEET